

Table of Contents

Executive Summary	i
1. Introduction.....	1
1.1 Study Rationale	1
1.2 Objectives	2
1.3 Study Process.....	2
1.3.1 Environmental Assessment and Master Planning Process.....	2
1.3.2 Adaptive Management of Stream Corridors	3
1.3.3 Consultation.....	5
1.4 Emergency Works in Context of the Master Plan.....	5
2. Steps 1 and 2 – Issue Assessment, Problem Confirmation and Assessment.....	5
2.1 Project Background	5
2.2 Previous Studies.....	6
2.2.1 Forty Steps to a New Don (MTRCA, 1994).....	6
2.2.2 Wilket-Milne Creek Regeneration Concept Plan (Aquafor Beech et al., 1999).....	6
2.2.3 Wilket Creek at Lawrence Ave. and Leslie St. – Geomorphological Study (PGL, 2001).....	7
2.2.4 Don River Wet Weather Flow Master Plan (MMM, 2003).....	7
2.2.5 TRCA Regional Monitoring Program – Geomorphic Component (PGL, 2003a).....	8
2.2.6 Wilket Creek at Lawrence Ave. and Leslie St. - Study Update (PGL, 2003b)	8
2.2.7 Wilket Creek - Edwards Gardens Fluvial Geomorphological Study (PGL, 2007).....	8
2.2.8 Don River Watershed Plan - Beyond Forty Steps (TRCA, 2009a).....	9
2.2.9 Don River and Central Waterfront Project EA Study (MMM, 2012)	9
2.2.10 Available Data.....	9
2.3 Characterization of Basin	10
2.4 Geology	10
2.5 Historical and Existing Land Use.....	11
2.5.1 Archaeology Assessments	11
2.5.2 Land Use	11
2.6 Channel Characterization	11
2.6.1 Reach Delineation	11
2.6.2 Reach WC-R1.....	14
2.6.3 Reach WC-R2.....	17
2.6.4 Reach WC-R3.....	21
2.6.5 Reach WC-R4.....	25
2.6.6 Reach WC-R5.....	28
2.6.7 Reach WC-R6.....	32
2.6.8 Reach WC-R7.....	36
2.6.9 Reach WC-R8.....	39
2.6.10 Reach WC-R9.....	43
2.7 Summary of Issues and Problem Definition	47
3. Step 3 – Past-Future Trends/ Disturbances	48
3.1 Past Trends/ Disturbances	48
3.1.1 Past Land Use and Infrastructure Change	48

3.1.2	Hydrological and Hydraulic Change	49
3.1.3	Geomorphological and Ecological Response.....	49
3.1.4	Historic Migration Analysis	49
3.1.5	Historic Erosion Protection Measures	53
3.1.6	Monitoring Cross Section	53
3.1.7	Erosion Pin Measurements	55
3.1.8	Historic Incision.....	56
3.2	Future Trends/Disturbances	56
3.2.1	Future Land Use and Infrastructure Change.....	56
3.2.2	Geomorphological and Ecological Trends.....	56
3.2.3	Climate Change	57
4.	Step 4 – Assessment of Channel Response	58
4.1	Rapid Field Assessment.....	58
4.2	Geomorphological Classification and Channel Evolution.....	61
5.	Step 5 - Present Stream Functions	63
5.1	Hydrology and Hydraulics.....	63
5.1.1	Hydraulic Modeling WC-R3	63
5.1.2	Hydraulic Modeling WC-R5	64
5.2	Geomorphic Evaluation	66
5.2.1	Detailed Surveys.....	66
5.2.2	Sediment Character.....	68
5.2.3	Erosion Thresholds.....	71
5.3	Characterization of Catchment and Biotic Communities	73
5.3.1	Environmentally Sensitive Areas (ESAs)	73
5.3.2	Ecological Land Classification (ELC).....	74
5.3.3	Regionally Significant Flora	78
5.3.4	Non-native Flora	79
5.3.5	Tree Preservation	80
5.3.6	Wildlife	82
5.3.7	Fish	84
5.3.8	Benthic Macroinvertebrates.....	86
5.3.9	Water Quality	87
5.3.10	Thermal Profile of the Catchment and its Tributaries.....	87
5.4	Archaeological Studies	88
6.	Step 6 – Forecast Ultimate Configuration	89
6.1	Channel Form	89
6.2	Cross Sectional Enlargement.....	89
6.2.1	Willet-Milne Creek Regeneration Concept Plan Analysis	90
6.2.2	Wet Weather Flow Master Plan Enlargement Ratio Technique.....	90
6.2.3	PARISH Monitoring Site (2002-2014)	91
6.2.4	WWFMP Reference Sites (2000-2011).....	91
6.2.5	Regional Hydraulic Geometry Relationships	92
6.2.6	Stable Width Threshold Analysis.....	92
6.2.7	Comparison of Results	93
6.3	Planform Adjustments.....	94
6.3.1	Meander Belt Analysis.....	94
6.3.2	Empirical Meander Geometry Relationships	97

6.4	Potential Intervention.....	99
6.4.1	Purpose	99
6.4.2	Design Parameters and Implementation	100
7.	Step 7 – Feasibility of Intervention	101
8.	Step 8 – Define / Evaluate Alternatives	102
8.1	Restoration Alternatives	102
8.2	Opportunities and Objectives	102
8.2.1	Wilket Creek Park; WC-R1 to WC-R3	102
8.2.2	Edwards Gardens; WC-R4	103
8.2.3	WC-R5.....	103
8.2.4	WC-R6.....	103
8.2.5	WC-R7	103
8.2.6	WC-R8 and WC-R9	103
8.3	Evaluation Criteria	103
8.4	Scoring.....	104
8.4.1	Do Nothing.....	105
8.4.2	Local Improvements	105
8.4.3	Channel Realignment.....	106
8.5	Significant Natural Features	106
8.6	Evaluation of Alternatives	107
8.6.1	Wilket Creek Park, WC-R1 to WC-R3	107
8.6.2	Edwards Gardens; WC-R4	111
8.6.3	WC-R5.....	114
8.6.4	WC-R6.....	119
8.6.5	WC-R7	123
8.6.6	WC-R8 and WC-R9	128
8.7	Consultation and Engagement	132
8.7.1	Schedule of Consultation.....	132
8.7.2	Feedback	132
8.7.3	Aboriginal Engagement	133
9.	Step 9 – Preferred Alternative	134
9.1	Description of Preferred Alternative and Concepts	134
9.1.1	Wilket Creek Park, WC-R1 to WC-R3	134
9.1.2	Edwards Gardens, WC-R4	135
9.1.3	WC-R5.....	136
9.1.4	WC-R6.....	137
9.1.5	WC-R7	137
9.1.6	WC-R8 and WC-R9	138
9.2	Mitigation Measures - Best Management Practices	140
10.	Update of Existing Conditions	142
10.1	Emergency Works Overview	142
10.1.1	Wilket Creek Park - Sites 6 and 7.....	142
10.1.2	Wilket Creek Park - Site 3 Phase I	143
10.1.3	Country Lane	144
10.2	Feasibility of Direct Intervention	145
11.	Step 10 – Implementation	146

11.1	Projects in the Wilket Creek Geomorphic System Master Plan	146
12.	Next Steps	150
12.1	Detailed Design Considerations	150
12.2	Ancillary Tasks.....	150
	12.2.1 Work on Private Property	150
	12.2.2 Agency Review and Permitting.....	150
	12.2.3 Mitigation	150
12.3	Construction.....	150
	12.3.1 Constructability, Access, ESC.....	150
	12.3.2 Construction Timing and Duration.....	151
	12.3.3 Materials and Cost Control	151
12.4	Monitoring Plan and Adaptive Management	151
13.	Study Summary	153
13.1	Overview of Report.....	153
13.2	Study Conclusions	153
14.	References	154

List of Figures

Figure 1-1: Study Area Map (Wilket Creek shaded).....	1
Figure 1-2: Adaptive Environmental Management Feedback Loop (adapted from MNR, 2002).....	3
Figure 2-1: Reach Delineation of Wilket Creek	13
Figure 2-2: WC-R1 Infrastructure Hazards.....	15
Figure 2-3: WC-R2 Infrastructure Hazards.....	18
Figure 2-4: WC-R3 Infrastructure Hazards.....	22
Figure 2-5: WC-R4 Infrastructure Hazards.....	26
Figure 2-6: WC-R5 Infrastructure Hazards.....	29
Figure 2-7: WC-R6 Infrastructure Hazards.....	33
Figure 2-8: WC-R7 Infrastructure Hazards.....	37
Figure 2-9: WC-R8 Infrastructure Hazards.....	40
Figure 2-10: WC-R9 Infrastructure Hazards.....	44
Figure 3-1: Historic Planforms - Wilket Creek Park and Edwards Gardens; WC-R1 to WC-R4.....	51
Figure 3-2: Historic Planforms - WC-R5 to WC-R9.....	52
Figure 3-3: TRCA D26 Monitoring Site.....	54
Figure 3-4: Cross-sectional Monitoring Results (2002-2014).....	55
Figure 4-1: Stream Evolution Model (adapted from Cluer and Thorne, 2013).....	62
Figure 5-1: Longitudinal Profile WC-R1.....	66
Figure 5-2: Longitudinal Profile WC-R2 and WC-R3.....	67
Figure 5-3: Longitudinal Profile WC-R5.....	68
Figure 5-4: Sediment Size Distribution WC-R1	69
Figure 5-5: Sediment Size Distribution WC-R2 and WC-R3	70
Figure 5-6: Sediment Size Distribution WC-R5.....	71
Figure 5-7: Proposed ESA Areas (adapted from City of Toronto, 2014).....	74
Figure 5-8: Riparian Sand/ Gravel Bars (BB01-a) located in WC-R1.	75
Figure 5-9: Open mineral bluff (BL01) located within the Wilket Creek corridor.	75
Figure 5-10: Cultural Mixed Coniferous Plantation (CUP3-h) found in WC-R9.....	76
Figure 5-11: Dry – Fresh Sugar Maple Deciduous Forest (FOD5) located in Wilket Creek Park.	76
Figure 5-12: Fresh - Moist Hemlock - Hardwood Mixed Forest FOM6-1) located in Wilket Creek Park.....	76
Figure 5-13: Marsh (MA) Community located north of Wilket Creek Park along the bottomlands.....	77
Figure 5-14: Open Water Community Bottomlands.	77
Figure 5-15: Ecological Constraints Map.....	81
Figure 6-1: Enlargement Ratio Versus Percent Imperviousness (adapted from MacRae and D'Andrea, 1999).....	90
Figure 6-2: Meander Belt Wilket Creek Park; WC-R1 - WC-R3.....	96
Figure 6-3: Meander Belt WC-R5 - WC-R9.....	97
Figure 6-4: Projected Planform based on Williams (1986).....	99
Figure 8-1: Channel Realignment WC-R5.....	117
Figure 8-2: Channel Realignment Options A and B	127
Figure 9-1: Proposed Wilket Creek Park Channel Realignment.....	135
Figure 9-2: Proposed WC-R5 Local Improvements and Channel Realignment.....	136
Figure 9-3: Proposed WC-R6 Local Improvements	137
Figure 9-4: Proposed WC-R7 Local Improvements and Channel Realignment.....	138
Figure 9-5: Proposed WC-R8 Local Improvements	139
Figure 9-6: Proposed WC-R9 Local Improvements	140
Figure 11-1: Overview Map of Proposed Rehabilitation of Wilket Creek	149

List of Tables

Table 1-1: Typical deliverables of the Planning and Assessment Stage	4
Table 1-2: Relationship between MEA (2011) and MNR (2002)	4
Table 2-1: Land Use within the Wilket Creek Subwatershed	11
Table 2-2: Summary of Wilket Creek Reach Characteristics	12
Table 3-1: Historic Channel Sinuosity	50
Table 3-2: Historic Migration Rates	53
Table 3-3: Cross-section monitoring results for Wilket Creek (2002-2014)	54
Table 3-4: Erosion pin monitoring results for Wilket Creek (2002-2010)	55
Table 4-1: WC-R1 Summary	59
Table 4-2: WC-R2 Summary	59
Table 4-3: WC-R3 Summary	59
Table 4-4: WC-R4 Summary	59
Table 4-5: WC-R5 Summary	60
Table 4-6: WC-R6 Summary	60
Table 4-7: WC-R7 Summary	60
Table 4-8: WC-R8 Summary	60
Table 4-9: WC-R9 Summary	61
Table 5-1: Flow Rates	63
Table 5-2: WC-R3 hydraulic modeling results for 19.35m ³ /s (modelled 2-year return).....	63
Table 5-3: WC-R5 hydraulic modeling results for 17.96m ³ /s (modelled 2-year return).....	65
Table 5-4: Summary of existing geomorphic conditions WC-R1	67
Table 5-5: Summary of existing geomorphic conditions WC-R2 and WC-R3	67
Table 5-6: Summary of existing geomorphic conditions WC-R5	68
Table 5-7: Sediment Summary WC-R1	68
Table 5-8: Sediment Summary WC-R2 and WC-R3	69
Table 5-9: Sediment Summary WC-R2 and WC-R5	70
Table 5-10: Summary of Critical Threshold Values	73
Table 5-11: Local scores and ranks for vegetation communities (TRCA, 2007).....	78
Table 5-12: Local scores and ranks for flora communities (TRCA, 2007)	78
Table 5-13: NHIC Flora data for the Wilket Creek corridor	79
Table 5-14: Non-native plant species identified in 2000 and 2004 biological surveys in study area	80
Table 5-15: Fauna observed by TRCA in study area, 2004	82
Table 5-16: NHIC Wildlife data for the Wilket Creek corridor	83
Table 5-17: Results of 2010 fisheries assessment within WC-R1 and WC-R3.....	84
Table 5-18: Fish Species List - Lower West Don River Subwatershed 1949-2005 (TRCA, 2009).....	85
Table 5-19: Categories used to evaluate water quality with the HBI (Hilsenhoff, 1987)	87
Table 5-20: Water Quality Indices for WC-R1 and WC-R3	87
Table 6.1: Enlargement Ratios between monitoring time periods.....	91
Table 6.2: Hydraulic Geometry Relationships	92
Table 6.3: Summary of projected stable channel widths under existing conditions	93
Table 6-4: Belt Width Analysis.....	96
Table 6-5: Empirical estimate of meander geometry for WC-R1 (Williams, 1986).....	97
Table 6-6: Empirical estimate of meander geometry for WC-R5 (Williams, 1986).....	98
Table 8-1: Evaluation of Restoration Options for Wilket Creek Park; WC-R1 to WC-R3.....	110
Table 8-2: Evaluation of Restoration Options for Edwards Gardens; WC-R4.....	113
Table 8-3: Evaluation of Restoration Options for WC-R5.....	118

Table 8-4: Evaluation of Restoration Options for WC-R6.....	122
Table 8-5: Evaluation of Restoration Options for WC-R7.....	127
Table 8-6: Evaluation of Restoration Options for WC-R8 and WC-R9.....	131
Table 9-1: Preferred Alternatives.....	134
Table 11-1: Summary of the Master Plan.....	147

Appendices

Appendix A: Archaeology Assessments
Appendix B: Hydraulic Analysis Memo
Appendix C: Ecological Classification Tables
Appendix D: Alternatives Evaluation Tables
Appendix E: Record of Public Consultation
Appendix F: Record of Aboriginal Engagement
Appendix G: General Cost Estimates of Intervention Options
Appendix H: Detailed Design Considerations